

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

DG537  
ENE  
1/2-1  
0.829 mi.  
4378 ft.

**WILLIAM E BRADEY  
25 BRIGHTON 4TH RD  
BROOKLYN, NY**

**NY Spills S117852474  
N/A**

**Site 2 of 2 in cluster DG**

**Relative:  
Higher**

**Actual:  
10 ft.**

**SPILLS:**

Name: WILLIAM E BRADEY  
Address: 25 BRIGHTON 4TH RD  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 1500836 / 2015-04-27  
Facility ID: 1500836  
Facility Type: ER  
DER Facility ID: 461763  
Site ID: 507008  
DEC Region: 2  
Spill Cause: Equipment Failure  
Spill Class: C3  
SWIS: 2401  
Spill Date: 2015-04-23  
Investigator: TJDEMEO  
Referred To: Not reported  
Reported to Dept: 2015-04-23  
CID: Not reported  
Water Affected: Not reported  
Spill Source: Institutional, Educational, Gov., Other  
Spill Notifier: Other  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2015-04-23  
Spill Record Last Update: 2015-04-27  
Spiller Name: DAVID GREISCH  
Spiller Company: POWER MECHANICS  
Spiller Address: 25 BRIGHTON 4TH RD  
Spiller Company: 999  
Contact Name: DAVID GREISCH  
DEC Memo: "4/23/15: Mahat DEC Mahat contacted Mr. David Greisch ( FDNY HazMat Resource @ 347.203.6886 ) inquiring more about the spill case. He mentioned the spill occure from the top of the temporary tank ( 6000 gallon AST ) due to a malfuntion of the valve. Spill has been stopped. DEP Hazmat was notified as the storm drain was impacted. Point of Contact : Rodger Gilbert 718.354.0792 \*\*\*\*\* Custodian DEC DeMeo responded to the spill. 4/23/15 TJD Recall - DeMeo met onsite with representatives of NYCCEM, SCA/DOE and contractor (PTC). A failed emergency shutoff on the transfer pumps failed to function as designed causing an overfill of the 3K AST temporary tank in roadway. FDNY responded, shut down the transfer pumps, dyked the pooled product in roadway with granular absorbents and applied spill pads to the affected area. FDNY had completed operations and departed site prior to DEC arrival. As a roadway catch basin was impacted, DEP was notified and responded to the location. All product was spilled to concrete/asphalt and PTC was onsite to remove contaminated absorbents placed by FDNY, wipe tank and clean debris in roadway, followed by a pressure wash of affected areas. Additionally, the affected catch basin was opened, cleaned of debris and oil/water mixture was recovered. Spill occurred during dry weather conditions and there was

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Remarks:

no significant migration of product requiring further investigation or cleanup. No further action is required. Spill closed."  
"6000 GALLON TANK THAT WAS OVER FILLED. SPILL LEAKED INTO THE CATCH BASIN. TRYING TO CONTACT THE OIL COMPANY TO UNLOAD SOME OF THE FUEL. CLEAN UP MEASURES IN PROGRESS. EXCESS FUEL BEING PUMPED INTO 55 GALLON DRUMS"

All Materials:

Site ID: 507008  
Operable Unit ID: 1256345  
Operable Unit: 01  
Material ID: 2259214  
Material Code: 0066A  
Material Name: unknown petroleum  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: 100.00  
Units: G  
Recovered: Not reported  
Oxygenate: Not reported